Approved For Release 2004/07/07: CIA-RDP66R00546R000100120050-7

P-1.2

23 January 1963

Present Common Ch

MEMORANDUM FOR:

The Special Group

SUBJECT:

Permission for a TACKLE Mission

to the Szechwan Basin

Two TACKLE missions directed at the Szechwan 25X1 Basin have failed because of camera malfunction. Permission is requested to mount another mission

at this target as soon as feasible.

The Hy Con camera experts through extensive 2. tests have determined that the cause of malfunction lies in the vacuum solenoid. This device which controls the movement of the film has been rebuilt to replace a cadmium lining with nickel. This replacement, thoroughly tested, will be installed before any further TACKLE missions are made. This should be accomplished by 23 January. The answer to why this fault has not shown itself in pervious years is obscure but it is believed associated with the age and protracted use of the equipment.

25X1

HERBERT SCOVILLE, JR. Deputy Director

25X1

(Research)

Approved For Release 2004/07/07 : CIA-RDP66R00546R000100120050-7

25X1

25X1

Approved For Release 2004/07/07: CIA-RDP66R00546R000100120050-7

Copy 1--Office of the Special Assistant to the President
for National Security Affairs
2--The Under Secretary of State for Political Affairs
3--Under Secretary of Defense
4--DCI
5--DDCI
6--Mr. Thomas A. Parrott
7--DDR
8--DDR
9--DDI (via
10--D/NRO (S)
11--AD/OSA
12--Intel/OSA
13--Special Group Officer/DDR
14--RB/OSA/DDR

25X1